


Connection/ Wiring Diagrams

Part Winding Start (Wye Only)

Speed: Single
 Phase: 3
 Typical Voltage: Dual 230/460
 Winding: Y only
 Special Feature:
 Part winding, start low voltage, 9 leads

Note: Normally this is a standard Star-Y dual voltage motor used for part winding start at 230V.



[Home](#) [Email](#)

Copyright © 2000 U.S. Electrical Motors, All rights reserved