


Connection/ Wiring Diagrams

Constant Torque (One Winding)

Speed: Two
Phase: 3
Voltage: Single voltage only
Winding: Single winding
Special Feature: Constant torque

Note: Normally provided on two speed units with speed ratio of 2 to 1.



[Home](#) [Email](#)

Copyright © 2000 U.S. Electrical Motors, All rights reserved