



Connection/ Wiring Diagrams

Variable Torque

Speed: Two
Phase: 3
Voltage: Single voltage only
Winding: Single Y
Special Feature: Variable torque

Note: Normally provided on two speed units with speed ratio of 2 to 1.



[Home](#) [Email](#)

Copyright © 2000 U.S. Electrical Motors, All rights reserved