


Connection/ Wiring Diagrams

One Wye (Two Winding)

Speed: Two
Phase: 3
Voltage: Single voltage only
Winding: Y - Y
Special Feature: Constant torque, variable torque or constant HP

Note: Two Windings provided on two speed unit not having speed ratio of 2 to 1.



[Home](#) [Email](#)

Copyright © 2000 U.S. Electrical Motors, All rights reserved