



## Connection/ Wiring Diagrams

### WYE Only

Speed: Single  
Phase: 3  
Voltage: Single Voltage Only  
Winding: Y only  
Special Feature:  
Neutral Brought out -  
4 leads (3 phase 4 wire)

**Note:** Phase voltage (lead to neutral) = line volts / Square Root of 3; provided only upon request.



[Home](#) [Email](#)

Copyright © 2000 U.S. Electrical Motors, All rights reserved