

Non-reversing motor starter Size 1 Three phase full
voltage Solid-state overload relay OLRelay amp range
5.5-22A 110-120/220-240VAC 60HZ coil Combination
type No enclosure

Further information

Information- and Downloadcenter (Catalogs, Brochures,...)

<http://www.siemens.de/industrial-controls/catalogs>

Industry Mall (Online ordering system)

<https://mall.industry.siemens.com>