

Non-reversing motor starter Size 4 Three phase full
voltage Solid-state overload relay OLRelay amp range
50-200A 110VAC 50HZ / 120VAC 60HZ coil
Combination type Indoor general purpose use

Further information

Information- and Downloadcenter (Catalogs, Brochures,...)

<http://www.siemens.de/industrial-controls/catalogs>

Industry Mall (Online ordering system)

<https://mall.industry.siemens.com>