

Non-reversing motor starter Size 5 Three phase full
voltage Solid-state overload relay OLRelay amp range
55-250A 440-480V 50-60HZ/DC coil Combination type
No enclosure

Further information

Information- and Downloadcenter (Catalogs, Brochures,...)

<http://www.siemens.de/industrial-controls/catalogs>

Industry Mall (Online ordering system)

<https://mall.industry.siemens.com>