

Two speed motor starter Two separate windings
(constant NEMA size 3 3-phase, 3-pole max rating
600VAC max HP 60HZ: 2/20 3/460V; 3/575V SS
Overload Control voltage 120/240VAC open

Further information

Information- and Downloadcenter (Catalogs, Brochures,...)

<http://www.siemens.de/industrial-controls/catalogs>

Industry Mall (Online ordering system)

<https://mall.industry.siemens.com>